



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
August 29, 2005

Supervisor 1027

Mine Name: Island Rock #1
Operator Name: John Bleazard
(Craig Smith)
Inspector(s): Lynn Kunzler, Daron Haddock
Other Participants: Craig Smith
Mine Status: Active, UNPERMITTED

Permit number: S/045/066
Inspection Date: July 15, 2005
Time: 8:45 - 9:15 am

Weather: Clear, Warm

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This inspection was conducted after receiving notification from the public that there was recent mining activity in this area. Since our database did not show any mine in the area, the inspection was scheduled.

Inspection Summary:

Upon arrival at the site, we found Mr. Craig Smith loading a truck with rock. It appeared that most of the rock was at or near surface, at the base of an exposed (bedded) outcrop. The rock being loaded did not appear to meet the criteria for a 'rock aggregate' exemption under the Act. We discussed the permitting and bonding requirements with Mr. Smith, and agreed that due to site conditions, the required reclamation surety could be reduced from our average cost per acre to \$500.00/acre. Photos were taken of the site, but are not attached to this document.

Conclusions and Recommendations:

Based on this inspection, it was determined that a mining operation did exist. A cessation order (MC-05-01-08(1)) was issued for conducting mining operations without a permit. Abatement required the submission of a NOI by August 1, 2005 and the reclamation surety by August 15, 2005.

Inspector's Signature [Signature]

Date: August 29, 2005

LK:jb

O:\M045-Tooele\S0450066-IslandRock\inspections\Insp-07152005.doc